
Maintain instrument: coolant, power,etc.
Keep eyes out of the plane of the laser beam.
Use appropriate beam blocks, beam tubes, & enclosures.
The Pathway towards Laser Safety
Don't contaminate the instrument.
Keep beams parallel to the table and in one plane.
No jewelry, watches, or loose long hair.
Keep food and drink out of the lab.
Proper eye protection for current wave-length.
No unprotected beams through walkways.
Do not defeat interlocks without permission from the PI or instructor.